



## Gerade Schott- Verschraubungen

Bestellzeichen: K

## Straight Bulkhead Connections

order code: K

## Unions doubles passe- cloison

Référence de commande: K

Rohr AD pipe OD Tube Ø ext.	PN	M	S	S <sub>1</sub>	S <sub>3</sub>	L <sub>1</sub>	L <sub>1</sub>	D <sub>max</sub>	L <sub>3</sub>	L <sub>3</sub>	kg für % ST kg for % pc. kg en %	Bestellzeichen order code Réf. cde
6	L 500 [2200]	M 12x1,5	17	14	17	22	7	16	42	27	6,7	K 6-L
8		M 14x1,5	19	17	19	23	8	16	42	27	8,4	K 8-L
10		M 16x1,5	22	19	22	25	10	16	43	28	11,0	K 10-L
12	400 [1700]	M 18x1,5	24	22	24	25	10	16	44	29	13,3	K 12-L
15		M 22x1,5	27	27	30	27	12	16	46	31	22,8	K 15-L
18		M 26x1,5	32	32	36	30	13,5	16	49	32,5	33,2	K 18-L
22	250 [1100]	M 30x2	36	36	41	33	16,5	16	51	34,5	41,5	K 22-L
28		M 36x2	41	41	46	35	18,5	16	52	35,5	52,5	K 28-L
35		M 45x2	50	50	55	40	18,5	16	58	36,5	80,0	K 35-L
42		M 52x2	60	60	65	42	19	16	59	36	119,3	K 42-L
6	S 800 [3400]	M 14x1,5	19	17	19	27	12	16	44	29	9,6	K 6-S
8		M 16x1,5	22	19	22	28	13	16	44	29	12,4	K 8-S
10		M 18x1,5	24	22	24	31	14,5	16	46	29,5	18,1	K 10-S
12	630 [2700]	M 20x1,5	27	24	27	31	14,5	16	47	30,5	21,0	K 12-S
14		M 22x1,5	30	27	30	35	17	16	50	32	29,0	K 14-S
16		M 24x1,5	32	30	32	35	16,5	16	50	31,5	31,0	K 16-S
20	400 [1700]	M 30x2	41	36	41	39	17,5	16	55	33,5	54,5	K 20-S
25		M 36x2	46	46	46	44	20	16	59	35	89,0	K 25-S
30		M 42x2	50	50	50	48	21,5	16	64	37,5	107,7	K 30-S
38		M 52x2	65	60	65	53	22	16	68	37	173,0	K 38-S

Hinweise zu Druck- und Temperaturangaben siehe Seiten I/9 + I/10 / Hints concerning pressure-information – see I/9 + I/10 / Informations sur les pressions – voir I/9 + I/10  
 L<sub>1</sub>+L<sub>3</sub> = Ungefährmaß bei angezogener Mutter / L<sub>1</sub>+L<sub>3</sub> = approximate length with nut tightened / L<sub>1</sub>+L<sub>3</sub> = longueur approximative, l'écrou étant bloqué